

From: [Jefferson, Matthew](#)
To: [Coltrain, Katrina](#); todd.downham@deq.ok.gov
Cc: [Powell, Dan](#); [Crumbling, Deana](#); [Bussey, Donald](#); [Gerard, Henry](#); [Rice, James](#); [Zarella, Paul](#); pappel@eaest.com
Subject: Wilcox Oil LSA & EBA Remedial Investigation: Daily Field Report #8
Date: Tuesday, November 7, 2017 9:41:11 AM

Daily Field Report #8

Wilcox Oil Superfund Site

November 7, 2017

Work completed on November 6, 2017:

- GPS all EBA and Road Test Samples (RTS) for new and expanded locations
- Completed the following: EBA DU 17 (30pt IS shallow step out from EBA DU 11) and EBA SUT 1,3 (9ft IS deep to bound EBA DU 3 – due north of the EBA building)
- Completed RTS with road classified as built roads (roads with gravel or asphalt/coke base), cut roads (roads cut through woods and unplanned), and berm roads (originally used as berm but now are roads). Roads are being analyzed due to higher than anticipated lead concentrations in the EBA and along LSA transects which have DUs or SUs near roads. A 100' section of the each type of road were sampled with 10 IS composited. A map of each location will be provided in the next daily field report.
- All areas have been sampled and field work is complete.
- Dried and disaggregated IS. Analyzed dried IS with Niton XRF and samples will be disposed on site per instructions provided by the EPA RPM.

Meetings:

- Health & Safety morning meeting led by Matt Jefferson (TIIB) with Don Bussey (ERT), Deana Crumbling (TIIB), Chris Kelly (SERAS), Jim Rice (ICF), and Paul Zarella (ICF).
- Gerald Ball (ERT) and Karla Guerrero (ERT) departed on Sunday.
- Scott Grossman (ERT) departed Saturday afternoon.
- Don Bussey (ERT) arrived Monday morning.

Upcoming Work:

- Will classify samples by soil type and characteristics for reporting
- Will dispose of all IS at the LSA 14,2 (within the LSA hot zone) per EPA RPM instructions
- Complete demobilization by COB
- Analyze, dry and sieve 4 remaining RTS with Niton XRF

Issues or problems encountered in the field:

- 4 shallow samplers still missing. Filed a missing package report with UPS on 10/26/17. POC: Teresa Jones
- The southeast side of the EBA (DUs 6,7 and 14) will be unbound based DUs running into a disposal area with empty drums and construction debris.

Matthew Jefferson

Environmental Engineer

EPA Headquarters – Office of Superfund Remediation and Technology Innovation

Office: (703) 603-8892

Cell: (703) 209-4784

Fax: (703) 603-9116

jefferson.matthew@epa.gov